

UST Service Provider List (Mountains)

Company				Listing Submitted	Area of state conducts work
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711		Phone (828) 664-9822 Fax (866) 425-2661 Website advancedenvironmentalsolutions.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company				Listing Submitted	Area of state conducts work
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711		Phone (828) 664-9822 Fax (866) 425-2661 Website		9/2/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company		Listing Submitted		9/2/2015		Area of state conducts work		
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711		Phone	(828) 664-9822				Coastal (East of I-95):	Yes
		Fax	(866) 425-2661				Central (West of I-95 and East of I-77):	Yes
		Website					Mountains (West of I-77):	Yes
Compliance Testing and Monitoring						UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	No		Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes		Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes		Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes		UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No		UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:	Yes				UST System Removal:		No	
Environmental Service Firms						Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No					
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No					
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No					
Oil and Solvent Recycling:	No	Other:						
Soil and Water Testing Lab:	No							

UST Service Provider List (Mountains)

Company			Listing Submitted	8/26/2015	Area of state conducts work
AES of Greenville PO Box 59 Greenville, NC 27835			Phone (252) 758-3311 Fax (252) 481-5814 Website www.aes-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company			Listing Submitted	12/9/2015	Area of state conducts work
Barrett PetroWorks LLC 809 Hillsfarm St. NE Lenoir, NC 28645			Phone (828) 729-5861 Fax Website		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company				Listing Submitted	9/8/2015	Area of state conducts work	
Blue Ridge Environmental Services, Inc. 2315 Kings Rd. Ext. Shelby, NC 28152				Phone (704) 482-2111 Fax (704) 482-4335 Website		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

Company				Listing Submitted	9/10/2015	Area of state conducts work	
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704				Phone (828) 277-0100 Fax (828) 277-0110 Website www.blecorp.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:	Trust Fund Projects				
Soil and Water Testing Lab:	Yes						

UST Service Provider List (Mountains)

Company				Listing Submitted	9/23/2015	Area of state conducts work	
Cape Lookout Environmental Sciences, PLLC 8005 Clear Brook Drive Raleigh, NC 27615		Phone (919) 757-7901 Fax Website CapeLookoutEnv.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	9/23/2015	Area of state conducts work	
Cape Lookout Environmental Sciences, PLLC 8005 Clear Brook Drive Raleigh, NC 27615		Phone (919) 757-7901 Fax Website CapeLookoutEnv.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		9/23/2015		Area of state conducts work	
Cape Lookout Environmental Sciences, PLLC 8005 Clear Brook Drive Raleigh, NC 27615		Phone	(919) 757-7901			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
		Fax					
		Website	CapeLookoutEnv.com				
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	9/24/2015	Area of state conducts work	
Cardno, Inc. 2725 E. Millbrook Suite 121 Raleigh, NC 27604		Phone (919) 871-0999 Fax (919) 871-0335 Website www.cardno.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
				Other:			
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company				Listing Submitted	#####	Area of state conducts work	
Cedar Rock Environmental, P.C. 807 Bullard Lane Graham, NC 27253		Phone (336) 376-0394 Fax (336) 376-0395 Website www.cedarrockenvironmental.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
				Other:			
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	8/27/2015	Area of state conducts work	
C-First, Inc. 1119 Beaumont Rd. Roanoke, VA 24019				Phone (540) 777-9111 Fax (540) 777-9112 Website www.c-firstinc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		Yes	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other: Wayne Dispensers and Verifone POS	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						
Company				Listing Submitted	9/9/2015	Area of state conducts work	
Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305				Phone (910) 574-4748 Fax 253-681-05 Website www.ustcomonline.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	Off	Overfill Prevention Equipment Operability Check:	Off	Dispenser Meter Repair/Calibration:		Off	
Containment Sump Testing:	Off	Statistical Inventory Reconciliation Services:	Off	Leak Detection Equipment Installation Servicing:		Off	
Corrosion Protection Design Experts:	Off	Spill Prevention Equipment Testing:	Off	Spill Bucket Installation Repair:		Off	
Corrosion Protection System Repairs:	Off	Tank Tightness Testing:	Off	UST Equipment Installation - Other:		Off	
Corrosion Protection System Testing:	Off	UST Internal Inspections (Integrity Assessments):	Off	UST Equipment Repair:		Off	
Leak Detection Equipment Operability Check:	Off	UST Internal Lining Inspections:	Off	UST System Installation - Complete Systems:		Off	
Leak Detection Monitoring Services:	Off	Other:		UST Piping/Sump Installation:		Off	
Line Tightness Testing:	Off			UST System Removal:		Off	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Off	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Off	UST Equipment Verification:	Off				
Environmental Engineer/Geologist Soil and GW Cleanu	Off	Waste Disposal and Treatment:	Off				
Oil and Solvent Recycling:	Off	Other:					
Soil and Water Testing Lab:	Off						

UST Service Provider List (Mountains)

Company			Listing Submitted	8/27/2015	Area of state conducts work
Cobb Environmental & Technical Services, Inc. P. O. Box 1602, Tupelo, MS 38802 871 South Green Street, Tupelo, MS 38804 Tupelo, MS 38804			Phone (662) 841-0995 Fax (662) 841-0810 Website www.cobbenv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	Yes
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company			Listing Submitted	9/23/2015	Area of state conducts work
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606			Phone (919) 233-8626 Fax (919) 233-8909 Website www.cohesion-inc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company				Listing Submitted	9/23/2015	Area of state conducts work	
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606				Phone (919) 233-8626 Fax (919) 233-8909 Website www.cohesion-inc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No			
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No			
Line Tightness Testing:	No			UST System Removal: <u>Yes</u>			
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	8/26/2015	Area of state conducts work	
CROMPCO, LLC 1815 Gallagher Road Plymouth Meeting, PA 19462				Phone (800) 646-3161 Fax (610) 278-7621 Website www.crompco.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration: <u>Yes</u>			
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing: <u>Yes</u>			
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair: <u>Yes</u>			
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other: <u>Yes</u>			
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair: <u>Yes</u>			
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems: <u>Yes</u>			
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation: <u>Yes</u>			
Line Tightness Testing:	<u>Yes</u>			UST System Removal: <u>Yes</u>			
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	9/16/2015	Area of state conducts work	
CSM Environmental, PLLC PO Box 99 Boonville, NC 27011				Phone (336) 367-4145 Fax (336) 367-4772 Website www.csmenvironmental.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No			
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No			
Line Tightness Testing:	No			UST System Removal: No			
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	9/4/2015	Area of state conducts work	
EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703				Phone (919) 596-0470 Fax (919) 596-0578 Website www.emsenv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No			
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No			
Line Tightness Testing:	No			UST System Removal: No			
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

UST Service Provider List (Mountains)

Company			Listing Submitted	Area of state conducts work	
Enviro Consulting 531 Pitts School Road NW Suite D Concord, NC 28027		Phone (704) 721-0101 Fax (704) 721-0102 Website www.envirocorp.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	UST Lining Installation	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company			Listing Submitted	Area of state conducts work	
Environmental Compliance Services of NC, PC 13504 South Point Boulevard, Unit F Charlotte, NC 28273		Phone (704) 583-2711 Fax (704) 583-2744 Website www.ecsconsult.com	9/10/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	Eclipse -Total Tank Compliance Services	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:	SPCC, SWPP, Due Diligence, 24/7 ER Hotline		
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company			Listing Submitted	8/31/2015	Area of state conducts work
EnviroTrac Ltd. 7343 West Friendly Avenue Greensboro, NC 27410			Phone (336) 763-6025 Fax Website www.envirotac.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	Yes			UST System Removal:	Yes
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	Yes				
Company			Listing Submitted	#####	Area of state conducts work
Envirovation Geologic Consulting and Mapping, PC PO Box 3425 Boone, NC 28607			Phone (828) 406-0772 Fax Website www.envirovationconsulting.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company				Listing Submitted	8/27/2015	Area of state conducts work	
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107		Phone (336) 725-5844 Fax (336) 725-6244 Website www.evocorp.net				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	1/8/2016	Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone (704) 853-0800 Fax (704) 853-3949 Website www.excelengr.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	8/27/2015	Area of state conducts work	
Fourstar Petroleum 1119 Beaumont Rd. Roanoke, VA 24019		Phone (540) 563-1022 Fax (540) 362-1802 Website www.fourstarpetro.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	Yes		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	Yes		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:	Wayne Dispensers and Verifone POS		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	9/13/2015	Area of state conducts work	
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111		Phone (303) 770-8884 Fax (303) 770-3636 Website www.GallowayUS.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:	UST System Design		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	8/28/2015	Area of state conducts work	
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28110		Phone (704) 845-4010 Fax (704) 845-4012 Website www.geologicalresourcesinc.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	9/17/2015	Area of state conducts work	
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156		Phone (770) 917-8846 Fax (770) 917-0921 Website www.harcoservices.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		<u>Yes</u>	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	9/11/2015	Area of state conducts work	
Highlands Environmental Solutions, Inc. 8410-D Falls of Neuse Road Raleigh, NC 27615				Phone (919) 848-3155 Fax (919) 848-4265 Website www.HESfast.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>			Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>			Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>
						Other:	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						
Company				Listing Submitted	9/18/2015	Area of state conducts work	
INENCO, Inc. 132 W. Statesville Ave. Mooresville, NC 28115				Phone (704) 662-8192 Fax (704) 662-8194 Website inencoinc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>
						Other:	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted #####	Area of state conducts work	
J&W Plumbing Inc. PO Box 1686 118 Stephens Road Morganton, NC 28655				Phone (828) 433-6364 Fax (828) 433-5534 Website	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No		Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No		Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No		Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No		UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No		UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
					Other:	
Environmental Service Firms						
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No			
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company				Listing Submitted #####	Area of state conducts work	
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012				Phone 4409336825 Fax Website www.jgdpe.com	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No		Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No		Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No		Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No		UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No		UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
					Other:	UST installation drawings
Environmental Service Firms						
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No			
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					

UST Service Provider List (Mountains)

Company				Listing Submitted	8/26/2015	Area of state conducts work	
Johnson, Spellman and Associates 350 Research Court Suite 130 Peachtree Corners, GA 30092				Phone (770) 447-4555 Fax Website www.jsace.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No			
Leak Detection Monitoring Services:	No	Other:	System design services - Engineering	UST Piping/Sump Installation: No			
Line Tightness Testing:	No			UST System Removal: No			
Environmental Service Firms						Other: System design services - Engineering	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	10/5/2015	Area of state conducts work	
Law Petroleum, Inc. 11025 Arlington Church Road Charlotte, NC 28227				Phone (704) 573-3535 Fax (704) 573-3535 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration: No			
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: <u>Yes</u>			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair: <u>Yes</u>			
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other: <u>Yes</u>			
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair: <u>Yes</u>			
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems: <u>Yes</u>			
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation: <u>Yes</u>			
Line Tightness Testing:	<u>Yes</u>			UST System Removal: <u>Yes</u>			
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	10/1/2015	Area of state conducts work	
Martin & Slagle Geo Sciences, P.A. P.O. Box 1023 24 Lookout Terrace Black Mountain, NC 28711			Phone (828) 669-3929 Fax (828) 669-5289 Website martinandslagle.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	9/29/2015	Area of state conducts work	
National Tank Monitor, Inc. P.O. Box 940 Vilonia, AR 72173			Phone (800) 643-8265 Fax (501) 796-3981 Website www.nationaltankmonitor.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	Yes			UST System Removal:			No
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company			Listing Submitted	8/26/2015	Area of state conducts work
Nationwide Construction Group 53861 Gratiot Ave Chesterfield, MI 48051			Phone (810) 533-2416 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other: General Contracting & New Fuel Station Construction		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company			Listing Submitted	8/27/2015	Area of state conducts work
NC PETROLEUM & CONVENIENCE MARKETERS 7300 GLENWOOD AVE. RALEIGH, NC 27612			Phone (919) 782-4411 Fax (919) 872-4414 Website WWW.NCPCM.ORG		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	UST ENGINEERING		
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company				Listing Submitted	Area of state conducts work
Nova Consulting Group, Inc. 442 South Main Street Suite # 7 Davidson, NC 28036				Phone (704) 258-5196 Fax Website http://novaconsulting.com/	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company				Listing Submitted	Area of state conducts work
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037				9/28/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company			Listing Submitted	9/2/2015	Area of state conducts work
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715			Phone (704) 619-1528 Fax (803) 802-2441 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			Listing Submitted	8/26/2015	Area of state conducts work
Pinnacle Environmental Management Support, Inc. 1100 Park Central Boulevard South, Suite 3600 Pompano Beach, FL 33064			Phone (954) 977-3775 Fax (866) 209-4401 Website www.pinnacleems.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	Trust Fund Claims Preparation & Mgmt		
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company			Listing Submitted	9/28/2015	Area of state conducts work
Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031			Phone (704) 892-8600 Fax (704) 892-8711 Website precisiontankservice.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company			Listing Submitted	10/5/2015	Area of state conducts work
Progress Environmental, Inc. 120 Fayette Street Winston-Salem, NC 27101			Phone (336) 722-9999 Fax (336) 722-9998 Website www.progressenvironmental.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company				Listing Submitted	9/2/2015	Area of state conducts work	
Protective Technologies, Inc. 711 Mill Street Camden, SC 29020		Phone (803) 424-0412 Fax (803) 424-0414 Website www.protectivetechnologiesinc.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	9/15/2015	Area of state conducts work	
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406		Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	9/8/2015	Area of state conducts work	
Royster Oil Company, Inc. PO Box 1467 720 S Lafayette St Shelby, NC 28150		Phone (704) 487-6344 Fax (704) 487-7811 Website www.roysteroil.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	10/1/2015	Area of state conducts work	
S&ME, Inc. 9751 Southern Pine Blvd Charlotte, NC 28273		Phone 7045234723 Fax 7045253953 Website www.smeinc.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	10/5/2015	Area of state conducts work	
Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208		Phone (704) 394-6913 Fax (704) 394-6968 Website www.shieldengineering.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	9/8/2015	Area of state conducts work	
Simonsen Law Firm, P.C. 106 E. Queen St. P.O. Box 848 Edenton, NC 27932		Phone (252) 482-2175 Fax (252) 482-1355 Website www.simonsenlawfirm.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:	Legal Services related to all UST issues	UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	10/1/2015	Area of state conducts work	
Singleton Environmental, Inc. PO Box 2012 1301 Sand Hill Road Enka, NC 28728		Phone (828) 667-5001 Fax (828) 667-0105 Website www.singletonenvironmental.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	8/27/2015	Area of state conducts work	
SouthEastern Petroleum Systems, Inc. 101 Lawton Road Charlotte, NC 28216		Phone (704) 394-3178 Fax (704) 394-3170 Website www.sepsusa.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes		
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes		
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:	Tank Cleaning and Biocide Treatments				
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	9/22/2015	Area of state conducts work	
SR&R Environmental, Inc. 49220 Highway 421 N. PO Box 221 Wilmington, NC 28402				Phone (910) 763-6274 Fax (910) 763-6132 Website www.srrenviro.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:	Vacuum Truck Service				
Soil and Water Testing Lab:	No						

Company				Listing Submitted	8/27/2015	Area of state conducts work	
Superior Services PO Box 982 Hendersonville, NC 28793				Phone (828) 698-6286 Fax (828) 698-6294 Website www.superiorservices.us		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:	UST Repairs, AST inspection, testing, repair	UST Piping/Sump Installation:		No	
Line Tightness Testing:	Yes			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	8/27/2015	Area of state conducts work	
Terracon Consultants, Inc.		Phone (704) 509-1777				Coastal (East of I-95): Yes	
2020 Starita Road		Fax (704) 509-1888				Central (West of I-95 and East of I-77): Yes	
Suite E						Mountains (West of I-77): Yes	
Charlotte, NC 28206		Website www.terracon.com					
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

Company				Listing Submitted	9/3/2015	Area of state conducts work	
Terraquest Environmental Consultants, P.C.		Phone (919) 563-9091				Coastal (East of I-95): Yes	
100 E. Ruffin Street		Fax (919) 563-9095				Central (West of I-95 and East of I-77): Yes	
Mebane, NC 27302		Website www.terraquestpc.com				Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	Area of state conducts work
The Clark Group dba Clark Environmental Services, P.O. Box 10136 4918 Wrightsville Avenue Wilmington, NC 28404				Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company				Listing Submitted	Area of state conducts work
The El Group, Inc. 2101 Gateway Centre Boulevard Suite 200 Morrisville, NC 27560				9/9/2015	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company				Listing Submitted	9/9/2015	Area of state conducts work	
The El Group, Inc. 2101 Gateway Centre Boulevard Suite 200 Morrisville, NC 27560		Phone (919) 657-7500 Fax (919) 657-7551 Website				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	9/2/2015	Area of state conducts work	
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708		Phone (888) 822-2431 Fax (803) 802-0561 Website www.ustcorrosion.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		9/2/2015		Area of state conducts work	
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708		Phone	(888) 822-2431			Coastal (East of I-95): Yes	
		Fax	(803) 802-0561			Central (West of I-95 and East of I-77): Yes	
		Website	www.ustcorrosion.com			Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						